

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**



ATTY DKT. No.: MRKS/0121
U.S. SERIAL No.: 10/664,584
FILED: SEPTEMBER 17, 2003
TITLE: TUBING CONNECTION ARRANGEMENT
INVENTOR: EVAN, ET AL.

CONF. No.: UNKNOWN

PAGE 1 of 4

1/4




Fig. 1



ATTY DKT. NO.: MRKS/0121
U.S. SERIAL NO.: 10/664,584
FILED: SEPTEMBER 17, 2003
TITLE: TUBING CONNECTION ARRANGEMENT
INVENTOR: EVAN, ET AL.

CONF. NO.: UNKNOWN

PAGE 2 of 4

2/4




Fig.2



ATTY DKT. NO.: MRKS/0121
U.S. SERIAL NO.: 10/664,584
FILED: SEPTEMBER 17, 2003
TITLE: TUBING CONNECTION ARRANGEMENT
INVENTOR: EVAN, ET AL.

CONF. NO.: UNKNOWN

PAGE 3 of 4

3/4




Fig.3



ATTY DKT. NO.:
U.S. SERIAL NO.:
FILED:
TITLE:
INVENTOR:

MRKS/0121
10/664,584
SEPTEMBER 17, 2003
TUBING CONNECTION ARRANGEMENT
EVAN, ET AL.

CONF. NO.: UNKNOWN

PAGE 4 of 4

4/4




Fig. 4




Fig. 5

Fig. 6